

**Inspection Photos**  
**Operator: BP America**  
**Location/API #: 067-06904**  
**Date: 8-21-2019**



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern fill slope from the northeastern project area facing southward.



Photo 3. View of area where concentrated run-off exits the well pad and stormwater BMP is failed.



Photo 4. View of musk thistle rosettes within the eastern project area.



Photo 5. View of reference area vegetation facing southward.