

Inspection Photos  
Location Name: LAMP 42-3  
API#: 05-071-06672  
INSP. #: 695101266



Colorado Oil & Gas Conservation Commission  
37.11379, -104.7585, 2082.0m, 117°  
2019/08/28 13:36:31



Colorado Oil & Gas Conservation Commission  
37.11377, -104.75851, 2083.0m, 171°  
2019/08/28 13:36:48

PHOTO 1: WELLHEAD

PHOTO 2: WELL SIGN

Inspection Photos  
Location Name: LAMP 42-3  
API#: 05-071-06672  
INSP. #: 695101266



**PHOTO 3: UNUSED EQUIPMENT (TBG & RODS). REMOVE  
UNUSED EQUIPMENT, COMPLY WITH RULE 603.f. CA DATE 9-  
28-9.**

**PHOTO 4: TRASH ON LOCATION SOUTH OF WELLHEAD.  
POLICE LOCATION FOR TRASH AND DEBREE AT REGULAR  
INTERVALS, COMPLY WITH RULE 603.f. CA DATE 9-28-19**

Inspection Photos  
Location Name: LAMP 42-3  
API#: 05-071-06672  
INSP. #: 695101266



**PHOTO 5: STORMWATER EROSION ON UP GRADE SIDE OF  
ROW SOUTH OF LOCATION. **INSTALL OR REPAIR BMP'S**  
**COMPLY WITH RULE 1002.f. CA DATE 9-28-19****