

Inspection Photos

Loc#451937

Operator: Sandridge

Inspection Number: 692401299

Inspection Date: 8/15/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to Northeast.

August 15, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Shiras CTB Loc#451937



Photo#2:
Debris collected in corner and along fence 6/27/19.



Photo#3:
Area has been cleaned and debris removed

August 15, 2019



Photos #4:
Non reportable spills.

August 15, 2019



Photo#5:
Breach at reservoir berm 6/27/19.



Photo#6:
Temporary repairs have been conducted. Insert,
Concerns remain.

August 15, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Shiras CTB Loc#451937



Photo#7:
View over Expansion area.

August 15, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Shiras CTB Loc#451937