

Location Name: Snyder 3 Spill ID 462754

Inspection Date: 08/21/2019



Photo # 1 – 05-121-08457



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Location Name: Snyder 3 Spill ID 462754  
Inspection Date:08/21/2019



**Photo #2 – Weeds on access road and around wellhead require mowing/control**



Location Name: Snyder 3 Spill ID 462754  
Inspection Date:08/21/2019



Photo #3 – Weeds along spill path require mowing/control



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources