

Inspection Photos

Loc#458790

Operator: Sandridge

Inspection Number: 692401302

Inspection Date: 8/16/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
View of Location to Northeast. Flare did not seem to be burning efficiently.

August 16, 2019



Photo#2:
Flare did not seem to be burning efficiently.



Photo#3:
Repairs at Northwest corner.



Photo#4:
Silt fence will soon be, once again, overwhelmed

August 16, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Oxbow Loc#458790



Photo#5:
Repairs at Northeast corner.



Photo#6:
Repairs at Northeast corner.

August 16, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Oxbow Loc#458790



Photo#7:
South edge of Pad; lines running East-West



Photo#8:
Stained soil at South edge of pad along lines laying on ground, running East-West.

August 16, 2019



Photo#9:
Overview of Location to West.

August 16, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Oxbow Loc#458790