

# *Inspection Photos*

*Loc#445005*

*Operator: Sandridge*

*Inspection Number: 692401304*

*Inspection Date: 8/16/19*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location from entry.

August 16, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Sandridge Surprise Loc#445005



Photo#2:  
Slopes/ topsoil stockpile are not stabilized, resulting in erosion, sediment migration and degradation.



Photo#3:  
Slopes/ topsoil stockpile are not stabilized, resulting in erosion, sediment migration and degradation.

August 16, 2019





Photo#4:

Slopes/ topsoil stockpile are not stabilized, resulting in erosion, sediment migration and degradation.

August 16, 2019




**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Sandridge Surprise Loc#445005





Photo#5:  
Weir area 6/26/19



Photo#6:  
Weir area has been repaired

August 16, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Sandridge Surprise Loc#445005