

**Inspection Photos**  
**Location Name: McElwain #4**  
**Location ID: 320264**



**Photo 3 YNK BTRY is approx.. 80' from WH**



**Photo 4 Produced water tank NFPA placards appear to not have been installed.**

**Inspection Photos**  
**Location Name: McElwain #4**  
**Location ID: 320264**



**Photo 1 WH**



**Photo 2 Separator has been moved 75 feet from WH**