

Inspection Photos
Location Name: McElwain #4
Location ID: 320264



Colorado Oil and Gas Conservation Commission
Aug 29, 2019 10:36:53

Photo 1 WH



Colorado Oil and Gas Conservation Commission
Aug 29, 2019 10:40:08

Photo 2 TNK BTRY

Inspection Photos
Location Name: McElwain #4
Location ID: 320264



Photo 3 Separator Weeds on location



Photo 4 stained soil inside separator house and mechanical issue.

Inspection Photos
Location Name: McElwain #4
Location ID: 320264



Photo 5 ECD and weeds on location




Photo 6 Unused equipment: electrical wiring and panel

Inspection Photos
Location Name: McElwain #4
Location ID: 320264



Colorado Oil and Gas Conservation Commission
 Aug 29, 2019 10:37:50

Photo 7 sales line riser



222348

STATION NO. _____

STATION NAME -33 MCELWAIN #4

STATIC RANGE 0-⁵⁰⁰ PSIG

DIFFERENTIAL RANGE 0-100 #

TEMPERATURE RANGE 0-150°

METER RUN SIZE 2.067

| DATE | ORIFICE SIZE | TEST DATE |
|----------|--------------|-----------------|
| 4-19-99 | 1.250 | 5-12-99/5-12-99 |
| | 1.250 | 11-9-99 |
| 2-13-15 | 1.500 | 2-26-02 |
| 6-16-17 | 1.500 | 6-13-15 |
| 12-15-17 | 1.500 | 6-16-17 |
| 6-4-18 | 1.500 | 12-15-17 |
| 12-16-18 | 1.500 | 6-4-18 |
| | | 12-16-18 |

Colorado Oil and Gas Conservation Commission
 Aug 29, 2019 10:39:19

Photo 8 Meter inside meter house

Inspection Photos
Location Name: McElwain #4
Location ID: 320264



**Photo 9 Stained soil around produced water tank.
Mechanical issue 2" valve**



Photo 10 unused equipment: Conductor pipe and PU