

Inspection Photos
Location Name: Silver Spur Minerals 35-2H
API: 05-057-06490



Location sign off of Hwy 14. (Note: phone number was not active on 9/3/2019).



Well sign. (Note: phone number was not active on 9/3/2019).

Inspection Photos
Location Name: Silver Spur Minerals 35-2H
API: 05-057-06490



Equipment stored on Location.



Equipment stored on Location.

Inspection Photos
Location Name: Silver Spur Minerals 35-2H
API: 05-057-06490



Propane tank not labeled or placard.



Tank signage, labels, and placards are illegible.

Inspection Photos
Location Name: Silver Spur Minerals 35-2H
API: 05-057-06490



Tank signage, labels, and placards are illegible.



Tank 0030, staining beneath hammer unions.

Inspection Photos

Location Name: Silver Spur Minerals 35-2H

API: 05-057-06490



Tank 0030, staining beneath hammer unions.



Valve with handle not blind plugged. Note: There was evidence of livestock accessing Facility.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Silver Spur Minerals 35-2H
API: 05-057-06490



55-gallon container of what appears to be antifreeze.



Chemical storage (antifreeze) in inadequate secondary containment, vegetation growth near equipment building.

Inspection Photos
Location Name: Silver Spur Minerals 35-2H
API: 05-057-06490



Fired equipment with vegetation growth near by.



Chemical storage (antifreeze) in inadequate secondary containment, vegetation growth near equipment building.

Inspection Photos
Location Name: Silver Spur Minerals 35-2H
API: 05-057-06490



Ice build up on equipment. Valve handles in place. (Note: there was evidence of livestock on the Location).



Evidence of livestock on the Location. Note: Valve handles in place at well head, tank battery, and on other equipment.

Inspection Photos
Location Name: Silver Spur Minerals 35-2H
API: 05-057-06490



Trash through out Location.



Trash noted in open container.

Inspection Photos
Location Name: Silver Spur Minerals 35-2H
API: 05-057-06490



Condensate tanks. Note: valve handle in place.



Some valves had protective boxes around them.