

Final Reclamation Inspection

August 29, 2019

Operator: BAYSWATER EXPLORATION AND PRODUCTION LLC - #10261

Location ID: 433862

Inspection Document #: 697500545

Weld County, CO

NWNE Section 29 T7N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Hirsch Pad 29-C
Location ID: 433862



Photo 1. Photo taken from the entrance of the well location access road, facing West. Crop appears to be reflective of reference crop areas along the access road but an evaluation was not performed at the well location due to crop height.

Inspection Photos
Location Name: Hirsch Pad 29-C
Location ID: 433862



Photo 2. Photo taken from the north tank battery location, facing South. Photo illustrates Operator has failed to perform Final Reclamation activities at the tank battery.