

Inspection Photos

API#057-06463

Operator: Sandridge

Inspection Number: 692401307

Inspection Date: 8/16/19





Photo#1:
Overview of Location to from entry to South.

August 16, 2019



Photo#2:
Facilities/equipment/debris on site.



Photo#3:
Facilities/equipment/debris on site.

August 16, 2019



Photo#4:
Noxious weeds on site

August 16, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge PA Buffalo Ditch API#057-06463