

Inspection Photos

API#057-06464

Operator: Sandridge

Inspection Number: 692401309

Inspection Date: 8/16/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to from entry to West.

August 16, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge PA Buffalo Ditch API#057-06464



Photo#2:
Facilities/equipment/debris on site.



Photo#3:
Facilities/equipment/debris on site.

August 16, 2019



Photo#4:
Noxious weeds on site

August 16, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge PA Buffalo Ditch API#057-06464