

Inspection Photos
Location Name: Duncan-Van Schaick UT 1 1
Location ID: 312822



Photo 1. Overview of location taken facing west. Annual weeds visible in photo.



Photo 2. Annual weeds and debris in tank battery.

