

Inspection Photos
Location Name: Tow Creek 13-11
Location ID: 316755



**Photo 1. Overview of location taken facing southeast.
Annual and noxious weeds visible in photo.**



Photo 2. Stained soil with fresh soil on top of it at wellhead.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Tow Creek 13-11
Location ID: 316755



Photo 3. Stained soil at pump jack motor.



Photo 4. Tank label sign knocked over, annual weeds in battery.

Inspection Photos
Location Name: Tow Creek 13-11
Location ID: 316755



Photo 5. Stained soil with overflowing bucket at tank base.



Photo 6. Close up of bucket and staining from photo 5.