

**Inspection Photos**  
**Location Name: McCallum Unit 100**  
**Location ID: 324660**



**Photo 1. Overview of location taken facing northwest.**



**Photo 2. Photo of wellhead inside housing, stained soil at wellhead.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources