

Government Lubauer Petroleum 46

API: 05-103-05365

Inspection: 679705311



Photo 1. Location.

Government Lubauer Petroleum 46

API: 05-103-05365

Inspection: 679705311



Photo 2. Well head.



Photo 3. Casing valve open.

Government Lubauer Petroleum 46

API: 05-103-05365

Inspection: 679705311



Photo 4. Bag attached to venting gas.



Photo 5. Battery sign.