

Inspection Photos
Location Name: Booth Pad
Location ID: 430168



Photo 1: Tank Battery Sign



Photo 2: Tank Battery

Inspection Photos
Location Name: Booth Pad
Location ID: 430168



Photo 3: Location



Photo 4: Produced water tank faded labeling



Inspection Photos
Location Name: Booth Pad
Location ID: 430168



Photo 5: Produced water tank missing labeling.



Photo 6: Missing labeling on produced water tank



Inspection Photos
Location Name: Booth Pad
Location ID: 430168



Photo 7: Disconnected gas meter houses.

