

Inspection Photos
Location Name: Green USX EE 13-15P
Location ID: 410128



Photo 1: Pumpjack sign



Photo 2: Pumpjack

Inspection Photos
Location Name: Green USX EE 13-15P
Location ID: 410128



Photo 3: Weeds



Photo 4: Weeds

Inspection Photos
Location Name: Green USX EE 13-15P
Location ID: 410128



Photo 5: Unused equipment