

Final Reclamation Inspection

September 2, 2019

Operator: SRC ENERGY INC- #10311

Location ID: 333287

Inspection Document #: 697500581

Weld County, CO

SWSE Section 12 T6N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: FLOCKHART #12-45
Location ID: 333287



Photo 1. Photo taken from the entrance of location, facing North. Photo illustrates the Operator has failed to reclaim the access road.

Inspection Photos
Location Name: FLOCKHART #12-45
Location ID: 333287



Photo 2. Photo taken from the well/tank battery location, facing West. Photo illustrates the Operator has failed to reclaim the well/tank battery location.