

Inspection Photos
Operator: Springdale Partners LLC
Location: Springdale 9
API #05-075-09256



1. Lease sign, Non working Emergency number

2. Wellhead, solar powered cathodic rectifier and vegetation