

Inspection Photos
Operator: Springdale Partners LLC
Location: Springdale 7
API #05-075-09254



1. Lease sign, invalid operator, Non working Emergency number



2. Wellhead, solar powered cathodic rectifier and vegetation