

Inspection Photos
Operator: Springdale Partners LLC
Location: Springdale 2
API #05-075-05861



1. Lease sign at access, Non working Emergency number

2. Wellhead and vegetation

Inspection Photos
Operator: Springdale Partners LLC
Location: Springdale 2
API #05-075-05861



3. Separator in shed, steel ring containment, weeds

4. Tank battery, weeds

Inspection Photos
Operator: Springdale Partners LLC
Location: Springdale 2
API #05-075-05861



5. Steel ring containment

6. Unmarked or locked out production risers