

Inspection Photos
Operator: Springdale Partners LLC
Location: Springdale Unit 16-9 (Baney State 16-9)
API #05-075-09247



1. Lease sign, Non working Emergency number



2. Battery equipment and weeds

Inspection Photos
Operator: Springdale Partners LLC
Location: Springdale Unit 16-9 (Baney State 16-9)
API #05-075-09247



3. Weeds



4. Pumping Unit

Inspection Photos
Operator: Springdale Partners LLC
Location: Springdale Unit 16-9 (Baney State 16-9)
API #05-075-09247



5. Battery equipment and weeds



6. Heated separator and weeds