

Inspection Photos
Operator: Springdale Partners LLC
Location: Springdale 1
API #05-075-05869



1. Lease sign, Non working Emergency number



2. Wellhead, separator shed, steel ring containment and weeds

Inspection Photos
Operator: Springdale Partners LLC
Location: Springdale 1
API #05-075-05869



3. Free water knockout and weeds



4. Separator shed and weeds