

Inspection Photos

Loc#335903

Operator: Laramie

Inspection Number: 692401314

Inspection Date: 8/20/19





Photo#1:
Overview of Location to North.

August 20, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie CC Loc#335903



Photo#2:

Areas no longer needed for Use have not been reclaimed. Figures are lined up 75Ft from Wells.

August 20, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie CC Loc#335903



Photo#3:
Further stabilization of Cut slopes is needed



Photo#4:
Further stabilization of Cut slopes is needed.

August 20, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie CC Loc#335903



Photo#5:
View of fill Slope.



Photo#6:
View of fill Slope.

August 20, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie CC Loc#335903