

Inspection Photos

Loc#335203

Operator: Laramie

Inspection Number: 692401316

Inspection Date: 8/20/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to Northwest.

August 20, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie CC Loc#335203



Photo#2:
Access road fill slope is unstable.

August 20, 2019



Photo#3:

Sediment trap and Culvert located to NE of access road entry and off East side of Pad need maintenance.

August 20, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie CC Loc#335203