

Lebauer 2  
API: 05-103-06369  
Inspection: 679705327



Photo 1. Location.

**Lebauer 2**  
**API: 05-103-06369**  
**Inspection: 679705327**



**Photo 2. Well head.**



**Photo 3. Casing open to atmosphere.**



**Lebauer 2**  
**API: 05-103-06369**  
**Inspection: 679705327**



**Photo 4. Bag attached to venting gas.**