

Harrison Smith 2
API: 05-103-01122
Inspection: 679705337



Photo 1. Location.

Harrison Smith 2
API: 05-103-01122
Inspection: 679705337



Photo 2. Well head.



Photo 3. Casing open to atmosphere.