


Lebauer 4  
API: 05-103-05352  
Inspection: 679705341



Photo 1. Location.

**Lebauer 4**  
**API: 05-103-05352**  
**Inspection: 679705341**



**Photo 2. Well head.**



**Photo 3. Casing open to atmosphere.**



**Lebauer 4**  
**API: 05-103-05352**  
**Inspection: 679705341**



**Photo 4. Bag attached to venting gas.**