

Inspection Photos
Location Name: Linnebur #6-13 tanks Battery
Location ID: 320469




Pic 1 spill



Pic 2 spill approx. 29 feet

Inspection Photos
Location Name: Linnebur #6-13 tanks Battery
Location ID: 320469



Pic 3 spill



Pic 4 spill approx. 30 feet

Inspection Photos
Location Name: Linnebur #6-13 tanks Battery
Location ID: 320469



Pic 5



Pic 6 stained soil/mechanical conditions

Inspection Photos

Location Name: Linnebur #6-13 tanks Battery

Location ID: 320469



Pic 7 emission control device appears to be burning gas from producing wells coming into location, Gas meter is LOTO



Pic 8 no netting around open flame



Inspection Photos

Location Name: Linnebur #6-13 tanks Battery

Location ID: 320469



Pic 9 stained soil/mechanical conditions



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources