

Inspection Photos
Location Name: Kawata 21-16 Pad
Location ID: 448030



Production facility



Unplacarded concrete vault

Inspection Photos
Location Name: Kawata 21-16 Pad
Location ID: 448030



Berm



Unplacarded concrete vault

Inspection Photos
Location Name: Kawata 21-16 Pad
Location ID: 448030



Open secondary containment



Open secondary containment

Inspection Photos
Location Name: Kawata 21-16 Pad
Location ID: 448030



Unused equipment



Unplacarded vault