

Inspection Photos
Location Name: Sledge C 9-29
Location ID: 309877



Photo #1 Wellhead, Sign, & Red PTA tag



Photo #2 Separator, ECD, & Meter Runs



Inspection Photos
Location Name: Sledge C 9-29
Location ID: 309877



Photo #3 Tank Battery



Photo #4 East Pit sign with no Capacity

