

Inspection Photos

Loc#383264

Operator: Laramie

Inspection Number: 692401319

Inspection Date: 9/6/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to Southwest.

September 6, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie CC Loc#383264



Photo#2:
Silt fence is not Properly installed.



Photo#3:
Silt fence is not Properly installed.

September 6, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources


Inspection Photos: Laramie CC Loc#383264



Photo#4:
Topsoil windrowed along top of Cut slope is not being protected.



Photo#5:



Photo#6:
Ditches need BMPs installed.



Photo#7:
Ditches need BMPs installed.

September 6, 2019