

Inspection Photos

09/09/2019

Operator: FOUNDATION ENERGY
MANAGEMENT LLC # 10112

Location ID: 447523
Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC # 10112

Location ID: 447523



Photo 1: Photo taken from the southwest end of the location, facing north. Photos 1-3 provide an overview of the location. Photos also show equipment remaining on location and final reclamation has not been conducted.

Photo 2: See comments under photo 1.

Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC # 10112

Location ID: 447523



Photo 3: See comments under photo 1.



Photo 4: Photo taken from the south end of the location. Photo shows Diffuse Knapweed rosettes on location. Operator appears to have conducted mowing operations. Mowing has not been a sufficient method in removing noxious weeds from location.

Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC # 10112

Location ID: 447523



Photo 5: Photo taken from the south end of the location. Photo shows Diffuse Knapweed on location. Diffuse knapweed as observed throughout location.



Photo 6: Photo taken from the south end of the location, facing west. Photo shows equipment has not been removed and location reclaimed.

Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC # 10112

Location ID: 447523



Photo 7: Photo taken from the south end of the location, facing north. Photo shows equipment has not been removed and location reclaimed.



Photo 8: Photo of Diffuse Knapweed observed on location.

Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC # 10112

Location ID: 447523



Photo 9: Photo taken from the east end of the location, facing north. Photo shows equipment has not been removed and location reclaimed.



Photo 10: Photo taken from the north end of the location, facing northwest. Photo shows equipment has not been removed and location reclaimed.

Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC # 10112

Location ID: 447523



Photo 11: Photo taken from the northeast end of the location. Photo shows Bindweed remains evident on location



Photo 12: Photo taken from the central area of the location. Photo shows diffuse knapweed (white flowers) remains evident on location.

Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC # 10112

Location ID: 447523



Photo 13: Photo taken from the adjacent reference area. Previous inspections required operator to conduct noxious weed management on the adjacent lands due to weeds spreading from the location. Noxious weeds remain evident on the surrounding adjacent lands.



Photo 14: Photo taken from the adjacent reference area, facing northwest. Previous inspections required operator to conduct noxious weed management on the adjacent lands due to weeds spreading from the location. Noxious weeds remain evident on the surrounding adjacent lands.