

# Inspection Photos

09/09/2019

Operator: FOUNDATION ENERGY  
MANAGEMENT LLC # 10112

Location ID: 330359  
Weld County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

## Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC # 10112

Location ID: 330359



**Photo 1:** Photo taken from the access road, facing west. Photo shows that access road has not been constructed or sufficient BMPs installed to allow for proper stormwater discharge to ensure existing access road remains in proper functioning condition.



**Photo 2:** Photo shows culvert at access road is not longer in proper functioning condition.



## Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC # 10112

Location ID: 330359



**Photo 3:** Photo shows areas where stormwater from the access road is discharging onto the adjacent lands. Sediment deposition evident.



**Photo 4:** Photo taken from the access road. Photo shows what appear to be Canada thistle is establishing on location.



## Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC # 10112

Location ID: 330359



**Photo 5:** Photo shows bindweed on access road.



**Photo 6:** Photo taken from the southwest end of the location. Photo shows Diffuse Knapweed (Plants with white flowers in photo) remains established on the location.



## Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC # 10112

Location ID: 330359



**Photo 7:** Photo taken from the southwest end of the location. Photo shows Diffuse Knapweed (Plants with white flowers in photo) remains established on the location.