

Inspection Photos

Location Name: 596-29C-65S96W 29NESW Pad

Location ID: #335943

Inspection Date: August 30, 2019



Photo #1 – Facility sign.



Photo #2 – Overview of tank battery and ECD located at SE corner of location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: 596-29C-65S96W 29NESW Pad

Location ID: #335943

Inspection Date: August 30, 2019



Photo #3 – Overview of wellhead and separator areas from west.

Note red wellhead signs.



Photo #4 – Marathon #596-29C-14 well sign.

Note: Emergency Contact Number (866-662-2378) is out of date. Number was tested on inspection date.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: 596-29C-65S96W 29NESW Pad

Location ID: #335943

Inspection Date: August 30, 2019



Photo #5 - Marathon #596-29C-14 wellhead where bubbling/gas leak were observed during 7/29/2019 Field Inspection (doc #698100050). No gas leaks were observed during 8/30/2019 follow-up inspection.

Note that cellar has been backfilled to prevent wildlife access.



Photo #6 – View of wellheads and chemical pump, looking northeast.

Note: backfilled cellars and red well signs.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: 596-29C-65S96W 29NESW Pad

Location ID: #335943

Inspection Date: August 30, 2019



Photo #7 – Heated horizontal separators on east side of location.



Photo #8 – Pump trailer with lined containment located east of tank battery.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: 596-29C-65S96W 29NESW Pad

Location ID: #335943

Inspection Date: August 30, 2019



Photo #9 – View of lined tank battery secondary containment area (north side).



Photo #10 – Diesel AST with secondary containment device located on west side of location.