

Inspection Photos
Location Name: John A. Kuzman Tank Battery
Location ID: 311327



Photo #1 TB sign



Photo #2 TB

Inspection Photos
Location Name: John A. Kuzman Tank Battery
Location ID: 311327



Photo #3 weeds growing around TB



Photo #4 Hoz.sep.

Inspection Photos
Location Name: John A. Kuzman Tank Battery
Location ID: 311327



Photo #5 PW tan lid appears to be open



Photo #6 PW Tank

Inspection Photos
Location Name: John A. Kuzman Tank Battery
Location ID: 311327



Photo #7 unused equipment.




Photo #8 unused equipment.

Inspection Photos
Location Name: John A. Kuzman Tank Battery
Location ID: 311327



Photo #9 unused unmarked riser no LOTO



Photo #10 unused unmarked riser no LOTO

Inspection Photos
Location Name: John A. Kuzman Tank Battery
Location ID: 311327



Photo #11 unused unmarked riser no LOTO



Photo #12 unused unmarked riser no LOTO

Inspection Photos
Location Name: John A. Kuzman Tank Battery
Location ID: 311327



Photo #13 unused unmarked riser no LOTO



Photo #14 gas meter