

Government Hayes 1
API: 05-103-07109
Inspection: 679705385



Photo 1. Location.



Government Hayes 1
API: 05-103-07109
Inspection: 679705385

trench



Photo 2. Well head.

Photo 3. 2" deep trench next to well head cellar.

Government Hayes 1
API: 05-103-07109
Inspection: 679705385




Photo 4. Well head sign.

Photo 5. Container label.

Tank Battery
Inspection: 679705385



Photo 6. Tank battery looking northwest.

Tank Battery
Inspection: 679705385



Photo 7. Tank battery looking southeast.

Photo 11

Tank Battery
Inspection: 679705385



Photo 9

Photo 10

Photo 8. Tank battery – Inadequate berms circled in yellow.

Tank Battery
Inspection: 679705385



Photo 9. Berm low spot for open top tank.



Photo 10. Berm height too short for crude tanks.

Tank Battery
Inspection: 679705385



Photo 11. Berm height too short for water tanks.



Photo 12. Propane tank.

Tank Battery
Inspection: 679705385



Photo 13. Tank label.

Photo 14. Battery sign.

Tank Battery
Inspection: 679705385



Photo 15. Crude oil tank valve.



Photo 16. Crude oil tank valve.

Tank Battery
Inspection: 679705385



Photo 17. North corner of water tank building.



Photo 18. East side of water tank building.

Tank Battery
Inspection: 679705385

Gas stream



Photo 19. Open top tank.

Photo 20. Pipes into open top blow down tank.

**Tank Battery
Inspection: 679705385**

Same tank



Photo 21. Water tanks looking southeast.

Photo 22. Opening on top of water tank looking west.

Tank Battery
Inspection: 679705385



Photo 23. Container at north corner of water building.