

Inspection Photos
Location Name: Lamb 33-24
Location ID: 310021



Photo 1: Wellhead Sign; Reflects different operator



Photo 2: Wellhead

Inspection Photos
Location Name: Lamb 33-24
Location ID: 310021



Photo 3: Tank Battery Sign; Reflects different operator



Photo 4: Location w/ Centralized Tank Battery

Inspection Photos
Location Name: Lamb 33-24
Location ID: 310021



Photo 5: No Labeling on North tanks



Photo 6: No labeling on H2O tank

Inspection Photos
Location Name: Lamb 33-24
Location ID: 310021



Photo 7: No Placard on (South) tanks



Photo 8: No placard on H2O tank

Inspection Photos
Location Name: Lamb 33-24
Location ID: 310021



Photo 9: Hole in tank battery (east) berm wall.



Photo 10: Hole in tank battery (west) berm wall.