



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Patrick Bateman (p.bateman@kosinm.com)
Submission Date:	Jul 22, 2019 9:34:09 AM MDT
Server Receive Date:	Jul 22, 2019 9:34:15 AM MDT
Reference Number:	20190722-18112351294
Location:	17 Rd 5500, Farmington, NM 87401, USA Jul 22, 2019 9:31:17 AM MDT [View Map]

Information

Name	p.bateman@kosinm.com
Date	Jul 12, 2019
Well Name	MCCAW, LEROY GAS UNIT B 1
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Clean up Operator Debris Replaced/Repaired Tank Signs

Photo of first corrective action completed



Completed work description Corrective Action 1

Photo of second corrective action completed



Completed work description of corrective action 2

Photo of well sign and cleaned up location

Added tank capacity to sign on location

Completed work description of corrective action 3
Completed work description of corrective action 4
Summary of all work completed

Cleaned trash and debris
Disposed of trash
Cleaned up trash and debris and added tank capacity to sign.