

Form Information

| | |
|----------------------|---|
| Form Name: | Compliance Follow Up Form |
| Submitter Name: | Patrick Bateman (p.bateman@kosinm.com) |
| Submission Date: | Jul 31, 2019 11:42:11 AM MDT |
| Server Receive Date: | Jul 31, 2019 11:42:24 AM MDT |
| Reference Number: | 20190731-18113186960 |
| Location: | 3601 N 1st St, Bloomfield, NM 87413, USA Jul 31, 2019 11:42:03 AM MDT [View Map] |

Information

| | |
|---|--|
| Name | p.bateman@kosinm.com |
| Date | Jul 15, 2019 |
| Well Name | RICHARDSON GAS UNIT 01-25 1 |
| Select State | Colorado |
| Work type | COGCC Inspection AR |
| Completed work description Corrective Action 1 | N/A |
| Completed work description of corrective action 2 | N/A |
| Completed work description of corrective action 3 | N/A |
| Completed work description of corrective action 4 | N/A |
| Summary of all work completed | Plunger and piping were noted as left on location. Production had already removed unwanted debris from pad. No further actions needed or taken. |