



Form Information

Form Name: **Compliance Follow Up Form**
Submitter Name: Cole Nichols (colen@horizonenvservices.com)
Submission Date: Aug 1, 2019 9:31:16 AM MDT
Server Receive Date: Aug 1, 2019 9:32:56 AM MDT
Reference Number: 20190801-18113271183
Location: 557 Airpark Dr, Durango, CO 81303, USA
Aug 1, 2019 9:31:04 AM MDT [[View Map](#)]

Information

Name colen@horizonenvservices.com
Well Name GEARHART GAS UNIT C 2
API Number 50670899700
Select State Colorado
Work type COGCC Inspection AR
Action Complete Clean Up Weed Debris

Photo of first corrective action completed



Completed work description Corrective Action 1 sign

Photo of second corrective action completed



Completed work description of corrective action 2 treated weeds

Photo of third corrective action completed



| | |
|---|---------------|
| Completed work description of corrective action 3 | treated weeds |
| Completed work description | na |
| Completed work description of corrective action 4 | na |
| Completed work description | treated weeds |
| Summary of all work completed | treated weeds |