



## Form Information

Form Name:	<b>Compliance Follow Up Form</b>
Submitter Name:	Cole Nichols (colen@horizonenvservices.com)
Submission Date:	Aug 7, 2019 8:28:37 AM MDT
Server Receive Date:	Aug 7, 2019 8:30:19 AM MDT
Reference Number:	20190807-18113705590
Location:	91 S Skylane Dr, Durango, CO 81303, USA Aug 7, 2019 8:28:28 AM MDT [ <a href="#">View Map</a> ]

## Information

Name	colen@horizonenvservices.com
Date	Aug 2, 2019
Well Name	GEARHART GAS UNIT C 1
API Number	50670742500
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions

Photo of first corrective action completed



Completed work description Corrective Action 1

Sprayed Kochia around equipment

Photo of second corrective action completed



Completed work description of corrective action 2

Sprayed Kochia and jointed goatgrass.

Photo of third corrective action completed



Completed work description of corrective action 3  
 Photo of fourth corrective action completed

Sprayed Kochia on pad



Completed work description  
 Completed work description of corrective action 4  
 Additional photos

Sprayed Kochia on pad  
 na



Additional photos



Completed work description  
Summary of all work completed

Sprayed Kochia populations on pad.  
Sprayed Kochia populations on pad