



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Cole Nichols (colen@horizonenvservices.com)
Submission Date:	Aug 13, 2019 7:37:49 AM MDT
Server Receive Date:	Aug 13, 2019 7:39:30 AM MDT
Reference Number:	20190813-18114156605
Location:	557 Airpark Dr, Durango, CO 81303, USA Aug 13, 2019 7:38:39 AM MDT [View Map]

Information

Name	colen@horizonenvservices.com
Date	Aug 12, 2019
Well Name	HOTT GAS UNIT 30-01 2
API Number	50670708700
Select State	Colorado
Work type	inspection
Action Complete	Compliance Inspection Actions Clean Up Weed Debris

Photo of first corrective action completed



Completed work description Corrective Action 1

treated canada thistle and kochia in rec area

Photo of second corrective action completed



Completed work description of corrective action 2

treated kochia

Photo of third corrective action completed



Completed work description of corrective action 3

clean pad

Photo of fourth corrective action completed



Completed work description

clean pad

Completed work description of corrective action 4

na

Summary of all work completed

treated canada thistle again. on schedule for a late fall treatment for canada thistle again.