



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Patrick Bateman (p.bateman@kosinm.com)
Submission Date:	Aug 23, 2019 1:55:34 PM MDT
Server Receive Date:	Aug 23, 2019 1:55:45 PM MDT
Reference Number:	20190823-18115261864
Location:	299 Howe Dr, Ignacio, CO 81137, USA Aug 23, 2019 1:55:04 PM MDT [View Map]

Information

Name	p.bateman@kosinm.com
Date	Aug 8, 2019
Well Name	GEARHART GAS UNIT B 2
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Grading/recontour Clean up Operator Debris

Photo of first corrective action completed



Completed work description Corrective Action 1

Erosional debris cleaned up from slope

Photo of second corrective action completed



Completed work description of corrective action 2

Erosional debris

Completed work description of corrective action 3

Completed work description of corrective action 4

Summary of all work completed

.

.

Leveled pad and cleaned up trash and debris.
Cleaned up netting in cut slope and re-contoured
slope. Checked signage on site and all rig anchors.