



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Patrick Bateman (p.bateman@kosinm.com)
Submission Date:	Aug 23, 2019 2:15:12 PM MDT
Server Receive Date:	Aug 23, 2019 2:15:21 PM MDT
Reference Number:	20190823-18115267308
Location:	2363 CO-151, Ignacio, CO 81137, USA Aug 23, 2019 2:14:39 PM MDT [View Map]

Information

Name	p.bateman@kosinm.com
Date	Aug 7, 2019
Well Name	SIMON LAND & CATTLE 22-1 4
Location Name (Other)	22-1 4&2
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Clean Up Contaminated Soils

Photo of first corrective action completed



- Completed work description Corrective Action 1
- Completed work description of corrective action 2
- Completed work description of corrective action 3
- Completed work description of corrective action 4
- Summary of all work completed

Cleaned soil around wellhead.

- .
- .
- .

Cleaned up contaminated soils around wellhead and backfilled. Disposed of soils properly and cleaned up all trash and debris.