

Inspection Photos

Location Name: Greenleaf Disposal

Location ID: 448823

Inspection Date: September 4, 2019



Photo #1 – Aerial view of the location (GISOnline Maps).



Photo #2 – View of the disposal well.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Greenleaf Disposal
Location ID: 448823
Inspection Date: September 4, 2019



Photo #3 – View of the two buildings on location. The building on the left is chemical storage and the building on the right is the pump house.



Photo #4 – View of the chemical storage building door.



Inspection Photos
Location Name: Greenleaf Disposal
Location ID: 448823
Inspection Date: September 4, 2019



Photo #5 – View of the pump house, the 3-inch and 4-inch flowline on the east side of the building, and the lined containment area with the filter socks and poly cube container.



Photo #6 – View of the 3-inch and 2-inch flowline on the west side of the pump house.



Inspection Photos
Location Name: Greenleaf Disposal
Location ID: 448823
Inspection Date: September 4, 2019



Photo #7 -View of the 2-inch flowline on the west side of the pump house.



Photo #8 – View of unused equipment, supports, pallet and a shovel.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Greenleaf Disposal
Location ID: 448823
Inspection Date: September 4, 2019



Photo #9 – View of vegetation on location.



Photo #10 - View of stained gravel beneath garage door on the pump house building.



Inspection Photos
Location Name: Greenleaf Disposal
Location ID: 448823
Inspection Date: September 4, 2019



Photo #11 - Photos of filter socks and poly cube tank within secondary containment.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources