

Inspection Photos
Location Name: NVega 1D Pad
Location ID: 334451 & Spill/Release ID: 467076
Inspection Date: September 4, 2019



Photo #1 – View of the location. The black dots represent spills, the one on the northwest side of the pad is Spill ID 467076 (GISOnline Maps).



Photo #2 – Location signs.

Inspection Photos

Location Name: NVega 1D Pad

Location ID: 334451 & Spill/Release ID: 467076

Inspection Date: September 4, 2019



Photo #3 – View of the excavation looking northwest.



Photo #4 – View of the excavation area looking northeast.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: NVega 1D Pad

Location ID: 334451 & Spill/Release ID: 467076

Inspection Date: September 4, 2019



Photo #5 – View of the clean, stockpiled soil for backfilling.



Photo #6 – View of the tank from the former tank battery.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources