

Inspection Photos
Location Name: VEGA USX /A03-05
Location #: 422947



Photo #1
Vega USX A03-05 (05-123-33459) Wellsite
Shut-In | SI
Weeds



Photo #2
Vega USX A03-05 Battery
Shut-down | Inactive
Weeds

Inspection Photos
Location Name: VEGA USX /A03-05
Location #: 422947



Colorado Oil & Gas Conservation Commission
40.52214, -104.54114, 1449.0m, 174°
09/12/2019 02:03:07 PM

Photo #3

Vega USX A03-05 Separator | ECD areas

Weeds