

## Inspection Photos Location #413453



Location



Location



## Inspection Photos Location #413453



Tank not labeled with capacity



Tank labeled with capacity by pumper on location





## Inspection Photos Location #413453



Unused equipment



Unused equipment removed by pumper



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos Location #413453



Unused equipment



Unused equipment removed by pumper



## Inspection Photos Location #413453



Line heater C/A



Line heater C/A



## Inspection Photos Location #413453



Debris C/A



Unused equipment C/A

